

Rebuilding a South Bend

My last lathe...

-


Well, this is the saga of my 9" Southbend model A long bed.

It started about 5 years ago when a family member said he had this lathe and wanted to know if I would be interested in it?

Well....I had 4 lathes at the time...not all in running condition....so adding another one to the mix seemed dubious at best....however, the price was right...."come and get it out of my shop"....so...I figured I'd at least fake interest and check it out.

Here's how I found her

How I got it.....



1951 SB 9 x 4 1/2 Model A

Originally sold to a tool and die shop
In Leominster.

It then spent 30 years in a auto repair
shop cutting commutators on
Truck generators

...pretty grungy.....



Steamer

How I got it.....



Stuff!.

The Plan

- Looked pretty good....I was wrong!
- Bed had a lot of wear....like .006 belly
- Tailstock was low .018"
- Tailstock quill was worn .004"
- Saddle had wear and abuse on it
- Worn shafts and bearings in many places
- But....was a long bed, and had some options..and I wanted a lathe this size.....
-Fish or cut bait time.....I went for it!



FIRST THING

[stevewb](#) on Ebay

Great kit of parts and instructions


Accurate

Good quality

Worth the money and then some!

I bought two kits...for spares....

Counter shaft bearings



Some lathes were bronze bushings
Some lathes were cast iron....

Mine was cast iron and had 0.062 wear on the
bore and shaft

I turned a new shaft, and bored the housing for
Sintered Bronze bushings and new oilers

Bored with a between centers boring bar on my
Boring table in the Logan

Counter shaft bearings

Between centers boring bar and boring table on the Logan



Counter shaft bearings



Counter shaft bearings



Boring complete.

Counter shaft bearings



Complete!

The Bed

- Didn't have a master straight edge 50 inches long
- Didn't have a surface plate that could handle a 50 inch straight edge
- What do do!!!!?

- Get it ground, and use the bed as the master, and then scrape everything to it.

The Bed




Forest City Grinding.

Dave Johnson Proprieter.

Approximately \$500 plus shipping

WE'll get back to this.....lots to do while at the Grinder!

Headstock and bearings



Headstock and bearings



The only part of the lathe
That didn't need anything
It was as far as I could measure
and discern...Like brand new

I did replace the fiber thrust washer
At the back of the late with a needle
Roller bearing. Worth the money
And It was a drop in replacement.


Disassembly instructions in book
Are accurate...follow them!...



Headstock and bearings



Change gear box




Looked pretty good
It had Worn shafts..one of them bad
Gears were good though
Nothing broken!

So I stripped it down




Change gear box

Simple green and hot water soak and it all comes off




Change gear box



Simple green and hot water soak and it all comes off


Change gear box



Change gear box



Apron




More worn parts
Worm gear housing had .06
Half nuts were half gone
Replaced bearings
Had to come up with some
Creative solutions for the
Worn housing though

Apron



Apron



This was going to require some Creative solutions!....all one piece.. Hard to get to.....what was the actual Center of the bore because it was No longer round...hard to tell!

Apron



I machined a bushing to a close fit with the Worm gear, and a nominal fit with the new Hole I was going to bore. You will notice the Slot on the OD. This bushing was then loctited into the new housing bore, and then bored to size. When to size, the slot was open. Then a standard wick could be fitted in place.


Apron



Set up on the boring table
Put the lead screw between
Centers through the apron
Adjusted the height and lateral
Position such that when the half
Nuts closed, there was no
Movement of the lead screw up
And down and side to side.


.....

Apron




Bushing going into place prior to boring

Apron



Bushing installed just prior to boring the bushing to size
Notice wick slot that is blind now. When bored to size, this
Slot opened up and a new factory oil wick was installed.

Apron



New bushing and worm gear
In place and meshed quite well

I also was able to find NOS
Half nuts to replace my worn
Ones. Good to go!



Apron




Tailstock and base




Existing one was 0.018" low and Worn with a severe "rocker".

Several alternative were thought of
Add a pad to the top or bottom
Shims (NO WAY!!!)
Lower the headstock...a lot of work


Or Make a new base...which is what I chose.




Tailstock and base



Tailstock and base



Tailstock and base




New base above


Old base below

Tailstock and base

Existing tailstock had dings from being dropped apparently...I re-scraped the bottom In process in this photo...



Tailstock and base



Tailstock and base



Tailstock and base



Tailstock and base



Tailstock and base



Tailstock and base



Tailstock and base



Tailstock and base




Tailstock bore



Set up a knee on the boring table. I bored the housing till it just cleaned up and no more being careful to align the base with the horizontal axis of the lathe.

Tailstock and base



Click to add title

Click to add description


I then made up a lap to smooth up the bore and make sure it was round.

I made a plug gage to determine actual size of the finished bore

Tailstock and base



Tailstock and base



Tailstock and base



The old quill had the nut pinned in place. I decided To machine the quill and leave just this Remnent as the nut for the new quill. I then installed It into position with Loctite. It worked quite well!

Tailstock and base



Lapping the quill to size.

You'll notice the roping chatter on the quill? It didn't show up until after I started to lap the quill to size. The part in the photo was slightly tapered with the left side being 0.0002" larger than the Right side. Once it was to size, the roping disappeared. I suspect that to be a artifact of the spindle bearings on the Logan.

Tailstock and base



The base/top assembly machined to be 0.005" high. From there it was scraped into alignment in the Horizontal and vertical plane....but not yet.....8-)

T slotted Cross Slide




I bought the T slotted cross slide casting from Metal Lathe Accessories.

This was some of the nicest cast Iron I've ever Machined. Great stuff, good machining allowance And a stable casting.

Definitely recommended

T slotted Cross Slide



T slotted Cross Slide



T slotted Cross Slide




T slotted Cross Slide

Two of my scraping masters




T slotted Cross Slide



T slotted Cross Slide




T slotted Cross Slide



The Bed

- ①
- MINIMUM STOCK REMOVAL
- EXACT .005 OR LESS STOCK REMOVAL
- VEE'S DONE IN ONE SETTING
- STRAIGHT .0004-.0009" TYP.



The key surfaces to be ground on the bed as conveyed to the grinding house.

The Bed











They are pretty when they come back....Tests showed it straight to about .0003"










The Bed



The Specification

TEST	PERMISSIBLE ERROR	TEST	PERMISSIBLE ERROR
	ACTUAL ERROR		ACTUAL ERROR
<p>1</p>  <p>TAILSTOCK WAY ALIGNMENT</p>	<p>Max. Reading along length of Bed 0.0005" in 48 in.</p> <hr/> <p>0.000</p>	<p>6</p>  <p>HEADSTOCK ALIGNMENT—VERTICAL</p>	<p>High at end of 12 in. Test Bar rising towards Tailstock End 0 to 0.0005"</p> <hr/> <p>0.000</p>
<p>2</p>  <p>SPINDLE CENTER RUNOUT</p>	<p>Total Indicator Reading 0 to 0.0004"</p> <hr/> <p>0.000</p>	<p>7</p>  <p>HEADSTOCK ALIGNMENT—HORIZONTAL</p>	<p>At end of 12 in. Test Bar 0 to + 0.0006" toward tool pressure</p> <hr/> <p>0.000</p>
<p>3</p>  <p>SPINDLE NOSE RUNOUT</p>	<p>Total Indicator Reading 0 to 0.0003"</p> <hr/> <p>0.000</p>	<p>8</p>  <p>TAILSTOCK SPINDLE ALIGNMENT—HORIZONTAL</p>	<p>Forward at end of Spindle when fully extended 0 to 0.0004"</p> <hr/> <p>0.000</p>
<p>4</p>  <p>CAM ACTION OF SPINDLE</p>	<p>Total Indicator Reading with Indicator on face of Spindle 0 to 0.0003"</p> <hr/> <p>0.000</p>	<p>9</p>  <p>TAILSTOCK SPINDLE ALIGNMENT—VERTICAL</p>	<p>High at end of Spindle when fully extended 0 to 0.0005"</p> <hr/> <p>0.000</p>
<p>5</p>  <p>SPINDLE TAPER RUNOUT</p>	<p>Total Indicator Reading at end of 12 in. Test Bar 0 to 0.0006" at end of Spindle Nose 0 to 0.0003"</p> <hr/> <p>0.000</p> <hr/> <p>0.000</p>	<p>10</p>  <p>TAILSTOCK TAPER ALIGNMENT—HORIZONTAL</p>	<p>End of 12 in Test Bar 0 to + 0.0008" toward tool pressure</p> <hr/> <p>0.000</p>

The Specification

TEST	PERMISSIBLE ERROR	TEST	PERMISSIBLE ERROR
	ACTUAL ERROR		ACTUAL ERROR
11  TAILSTOCK TAPER ALIGNMENT—VERTICAL	High at end of 12 in. Test Bar 0 to 0.0005" <hr/> 0.000	16  WORK MOUNTED IN CHUCK	Max. deviation from true roundness 0.0001" Must turn cylindrical 12 in. length of workpiece 0.0008" <hr/> 0.000
12  VERTICAL ALIGNMENT OF HEAD AND TAIL CENTERS	High at Tailstock 0 to 0.0008" <hr/> 0.000	17  WORK MOUNTED IN CENTERS	Must turn cylindrical on a 12 in. length of workpiece 0.0004" <hr/> 0.000
13  LEAD SCREW CAM ACTION	Maximum 0.0003" <hr/> 0.000	18 LEAD SCREW LEAD PER FT.	$\pm 0.001"$ <hr/> 0.00
14  CROSS SLIDE ALIGNMENT	To face hollow or concave only on 12 in. diameter 0 to 0.0005" <hr/> 0.000	19 BACK LASH ON CROSS FEED SCREW ON COMPOUND REST SCREW	0.004" <hr/> 0.00 <hr/> 0.004" <hr/> 0.00
15  FACE PLATE RUNOUT	On diameter 0 to 0.0005" on face at normal diameter 0 to 0.001" <hr/> 0.000 <hr/> 0.00	20 INDEXING OF SQUARE TURRET	Indicator Reading 0.001" <hr/> 0.00

Scraping sequence from here.


- Compound top.
- Compound Base to compound top using compound top as a gage
- Compound base to top of T slotted cross slide using T slotted cross slide as the gage
- Cross slide dovetail to T slotted cross slide using T slotted cross slide as a gage
- Saddle geometry (parallel to ways and cross slide dovetail perpendicular to axis of saddle travel

Compound top and compound base



The flat ways of the compound showed to be still flat and in good condition. The top of the compound was not parallel to the base, so I scraped it in to within 0.0005". The ways on the compound base mated well with the Compound. Little work was needed

Compound base to Cross slide



Notice the un marked area near the Nose of the compound. This is wear as A result of chips getting under the Compound and wearing away the surface

In this case it was about 0.001" but it Covered about 180 of arc at the front of The compound base. This can Contribute to chatter by making the Compound less stiff. Clean you cross slide Before you move it!....

MARKING SHOW HEAVY FOR PHOTOGRAPHIC REASONS

Saddle dovetail way to T slotted cross slide



The saddle dovetail was a complete mess Very worn with ridges This photo was After several passes. Using the T slotted Cross slide as a gage for both surfaces Of the dovetails. There is enough float in The leadscrew nut in the vertical direction To accommodate quite a bit of adjustment.

About .005" needed to come off.

Saddle to the Bed




The saddle geometry should be parallel in both directions to the leveling surfaces of the lathe.

On the Southbend, those surfaces are the tops of the V Way's within $.0005''/12''$ in both directions.

Additionally, the cross slide master dovetail should be square to the axis of the lathe to within $0.0005/12''$


Checking the squareness of the cross slide dovetail to the axis of the lathe



Using precision gage pins in the dovetail
And lightly clamping the precision square
To the dovetail .

.0005"/12

Checking level



Level needs to be checked every time you start work on the lathe. Only after careful leveling can any measurements be taken.

Here the bed is being checked for level. I have 123 blocks and know good parallels set up on saddle flat ways to check level in both directions. To determine how much needs to come off, it is useful to install shim stock under the parallels near the saddle V ways.

The two set ups for checking level



Tools of the trade



Lastly. The headstock and tailstock alignment



Headstock and tailstock
End of bar up and to the front by 0.0005"/12"

Initial reading were not good!



After much work on the headstock ways



After much work on the headstock ways




Setting the tailstock height




Tailstock point up and towards the front
 $0.0005''/12$ and $0.000/0.001''$ higher than the
Headstock.

Checking concavity



Finished Lathe



Additional items

- The saddle rack needed to be shimmed down 0.03"
- I replaced the standard switch with a VFD drive WORTH IT!
- I outfitted the lathe with a bunch of tooling and new chucks

Tooling

