



DESCRIPTION OF SHAPER TOOL HOLDERS AND SHAPER TOOLS



Photo by courtesy of J. H. Williams & Co.



UNIT T 52 (C)

Parts I and II Pages 151 - 166

DESCRIPTION *of* SHAPER TOOL HOLDERS

OBJECTIVES OF UNIT

1. To become familiar with the terminology used with tool holders.
2. To describe the various types of tool holders used for shaper work.
3. To become familiar with manufacturer's designations of tool-holder styles.

INTRODUCTORY INFORMATION



The use of tool holders instead of solid forged tools in the machine-tool industry was principally a matter of economy. The first attempts to hold tools in holders, although ingenious, allowed the tool to slip under heavy cuts and often lacked the rigidity so necessary for general use.

With the introduction of more expensive steels for cutting tools, much money was invested in the production of costly forged tools, as considerable time was required to forge, grind, and shape these tools. In addition, waste was unavoidable, for when the tools became too short to be held in the machine, they were discarded and eventually scrapped.

Gradually, as design improvements in tool holders were made, the use of these devices was extended. As a result of improved design, tools are securely and solidly held in tool holders, grinding has been reduced to a minimum, forging is unnecessary, and much waste has been eliminated. Although proportionately larger and stronger tool holders are designed for the larger machines, solid tools are still extensively used in the heavy machine-tool industries.

In addition to standard tool holders, there are those which can be purchased in sets. The sets contain a number of standard tools or bits which fit into a special holder. A set of these cutters is adequate for the usual shaper operations. Extra cutters usually may be purchased, and special ones can be made to order.

The American Society of Mechanical Engineers has adopted a set of definitions which apply to all single-point tools, including tool holders. As these definitions have not been adopted by all users and manufacturers, special attention must be given to how the terms are applied in each case.

DESCRIPTION OF TOOL HOLDERS

SIZE AND STYLE

To the shaper operator, the size of the tool holder used depends principally upon the size of the shank which will fit into the tool post of the machine. It is also necessary for the operator to decide whether or not the tool holder should be straight or offset, right-hand or left-hand; and to select the style of holder to suit the shape of the tool.

The straight-shank tool holder (Fig. 200) holds the tool parallel with the sides of the tool holder in contrast to the bent style (Fig. 201) which holds the tool at an angle with the slides. These tool holders also may be left or right (Fig. 201) depending upon the inclination of the tool either to the left or to the right of the work.

According to the American Standards as issued by the American Society of Mechanical Engineers and published in the American Machinists' Handbook, "A bent tool has the point bent to the left or right (Fig. 201) to make its operation more convenient. These tools are called left-bent tools if the point is bent to the left when looking at the tool from the point end with the face upward and the shank pointing away, and vice versa."

As a tool holder can be classified as a tool shank, this definition can be applied to a tool holder. Conventional usage, however, has not yet entirely adopted the definition, and for this reason four examples of two leading tool-holder manufacturers' products are shown in Fig. 202.

It should be noticed also that the term offset, instead of bent, is used to describe these holders.

The tool holder shown at (A) is designated as a right-hand offset tool holder; the one illustrated at (B) is a left-hand offset. The tool holder shown at (C) which holds a side-cutting tool is also a left-hand offset holder, although it is bent in the direction opposite to that of (B).

FIG. 200




FIG. 201





FIG. 202



Notwithstanding that the tool holder is "bent" to the opposite side compared with the one portrayed at (B), the tool which it holds will cut on the same side of the work. The tool holder shown at (D) is correspondingly a right-hand offset side-cutting tool holder.


The style of tool holder is also influenced by the cross-sectional shape of the tool (Fig. 200). It is understood that the tool is selected first to suit the style of cut, the nature of the material, and the kind of work.

Tool holders are designated by a manufacturers' number, usually with a letter placed either before or after the number. In other instances, a letter may be placed both before and after the number. The letter (S), (R) or (L) after the number indicates that the holder is straight, right-hand, or left-hand. The letter before the number frequently is the manufacturer's identification of the style of cutter. For example, a designation T-2-S would indicate that the tool holder is to be used to hold a $3/8$ " square tool bit and has a $5/8$ " x $1-1/2$ " x 8" straight shank. This would fit in a tool post with a maximum tool capacity of $7/8$ " x $1-1/2$ ".

TYPES OF TOOL HOLDERS


Tool holders may be classified according to the method of holding the tool in relation to the shank of the holder: (1) those which hold the tool parallel (horizontal) with the shank of the holder; (2) those which incline the tool at a slight angle with the shank; and (3) those which incline the tool at a steep angle with the shank.

Each of the three holders illustrated in Figure 200 is designed to hold the tool parallel with the shank of the tool holder. The tool to be used in these three tool holders is ground to the required shape and with the necessary clearances. Unless the tool is held parallel, the angle at which the point of the tool is presented to the work will be changed and the clearances also will vary.




An exceedingly handy holding device is the shaper-and-planer tool holder shown in Fig. 203. The tool is held parallel with the shank, but may be set at almost any angle to cut on the right- or left-hand side of the work. The tool holder may be held in the shaper in the conventional manner (Fig. 204) with the cutting edge ahead of the supporting surface, or the tool holder may be turned around to act as a gooseneck tool with the cutting edge behind the fulcrum (Fig. 205). In the former case, the tool has a tendency to spring into the work when cutting, whereas the spring of the tool is away from the work when it is held in the latter position.

As the tool is held parallel with the shank of the tool holder, the clearances and angles are easily determined and ground without having to take into consideration the inclined angle of the tool (Fig. 206).



In the second group of holders the tool is inclined at a slight angle. The slight angle at which the tool is held, called the tool-holder angle, should be such that it will eliminate, as much as possible, grinding the top of the tool. For shaper work, a satisfactory tool-holder angle is 15° (Fig. 206). The tool grinding in this case gives the tool both front and side clearance.


The remaining two examples in this classification (Fig. 207) incline the tool at a steep angle which should correspond to the most satisfactory clearance angle for the front of the tool. This type of tool holder, however, while not extensively used for general shaper work, has some merit when used to hold formed tools. The tool in this case can be ground on the top without changing the contour of the tool if the top surface is always ground at the same angle.




CLAMPING METHODS

Two principal methods are used to clamp the tool in the shaper tool holder: first, a direct clamping action caused by the pressure of a screw; second, a wedging action produced either by a cam or by a drawbolt.

An example of the first method is shown in Figures 208 and 209. A tool is inserted in a rectangular or square hole in the front of the holder and is forced down by the direct pressure of the screw.






In the second case, the tool is wedged against the bottom ledge of the tool holder by a cam action (Fig. 210). As the cam is turned with a wrench it presses downward against the tool in such a direction that, as the cutting action of the tool tends to force the tool into the tool holder, it wedges tighter as the pressure increases. The tool can be easily released by turning the cam in the direction opposite to that indicated by the arrow.

The drawbolt is another adaptation of the wedging action which also can be used very effectively with flat tools (Fig. 211). The cutter is placed in a slot in the side of the tool holder and is held in position with a tapered-head bolt with a flat side. As the bolt is drawn in, the tapered surface forces the bolt downwards and the pressure of the flat side of the head on the tool holds it in place.

Fig. 212 and Fig. 213 illustrate two other methods of holding the tool in the tool holder.


There are also on the market patented sets of tools and tool holders which have many convenient features. The set illustrated in Fig. 214 is made especially for shaper work.



DESCRIPTION *of* SHAPER TOOLS

OBJECTIVES OF UNIT

1. To understand the terminology used with cutting tools.
2. To become familiar with various shapes of tools.
3. To visualize and understand the angles of clearance, the angles of rake, and the lip angle of the tool.



INTRODUCTORY INFORMATION

Tools used in the shaper may be forged or ground to shape from solid steel bars or they may be smaller pieces of steel which are held and clamped in a tool holder.

The shape of the tool varies considerably with the character of the work. To give examples of the various shapes of tools for every purpose and at the same time to satisfy every individual mechanic's preference for form would be extremely difficult. In addition, the terms applied to single-point tools and tool holders are not entirely consistent. Although attempts have

been made to standardize these terms, conventional usage so far has frustrated attempts to apply them in every case.

There are certain principles, however, which the beginner must understand before he can use and grind cutting tools intelligently. For example, a tool may cut well for general work, but may not be satisfactory for sustained, heavy-duty production cuts.

The same caution should be observed in this unit regarding terminology as was followed with tool holders. The terms adopted by the American Standards Association have not been accepted by all users and manufacturers. Therefore, some explanation may be necessary when standard terms differ from those in conventional use.

It should be understood that changes of this character take time and often require considerable expense on the part of manufacturers. Eventually, the terms and processes which are best for the industry as a whole will finally be adopted.

CUTTING TOOL TERMINOLOGY

The shaper tool, or cutter, is in most cases a piece of high-grade steel which is shaped, hardened and ground to a cutting edge. It is securely held in the tool head of the shaper and made to pass across the work to take a series of cuts.

The tools may be forged from steel bars or they may be smaller pieces of steel inserted in a tool holder. The cutters are usually square or rectangular in shape, except in cases where tools are made in sets to fit special types of tool holders.

The shape or form of the tool depends chiefly upon the shape of the cut. It may also be influenced by the kind of finish required and the kind of material to be machined. The rake, the cutting angle, and the clearances, on the other hand, depend principally upon the nature of the material. All of the foregoing considerations are governed by certain basic underlying principles which have been determined as a result of experimentation and observation.

A discussion of cutting tools is better understood if some of the terms used to describe them are defined. The following American Standards' definitions apply to some of the more common terms used in connection with single-point cutting tools.

- POINT** -The point is all that part of the tool which is shaped to produce the cutting edges and face (Fig. 215).
- SHANK** -The shank is that part of the tool on one end of which the point is formed or the tip or bit is supported. The shank in turn is supported in the tool post of the machine (Fig. 215).









FIG. 215

- FACE** -The face is that surface on which the chip rolls or flows as it is cut from the work (Fig. 215).
- CUTTING EDGE** -The cutting edge is that portion of the face edge along which the chip is separated from the work. The cutting edge consists usually of the side-cutting edge, the nose radius and the end-cutting edge (Fig. 215).
- SHAPE** -The shape of the tool is the contour of the face when viewed in a direction at right angles to the base (Fig. 215).
- WORKING ANGLES** -The working angles are those angles between tool and work which depend not only on the shape of the tool, but also on its position with respect to the work.
- CUTTING ANGLES** - The cutting angle is the angle between the face of the tool and a tangent to the machined surface at the point of action. It equals 90° , minus the true-rake angle (Fig. 216).
- LIP ANGLE** -The lip angle is the included angle of the tool between the face and the ground flank measured in a plane at right angles to the cutting edge. When measured in a plane perpendicular to the cutting edge at the end of the tool, it is called the end lip angle. When measured at the point of chip flow, it is called the true lip angle (Fig. 217).
- BACK-RAKE ANGLE** -The back-rake angle (Fig. 218) is the angle between the face of a tool and a line parallel to the base of the shank or holder. The angle is positive if the face slopes downward from the point toward the shank, and is negative if the face slopes upward toward the shank (Fig. 218).



- END-RELIEF ANGLE** -The end-relief angle is the angle between the portion of the end flank immediately below the cutting edge and a line drawn through that cutting edge perpendicular to the base. It is measured in a plane parallel to the center line of the point (Fig. 219).
- SIDE-RELIEF ANGLE** -The side-relief angle is the angle between the portion of the flank immediately below the cutting edge and a line drawn through this cutting edge perpendicular to the base. It is measured in a plane at right angles to the center line of the point (Fig. 220).
- SIDE-RAKE ANGLE** -The side-rake angle is the angle between the face of a tool and a line parallel to the base. It is measured in a plane at right angles to the base, and at right angles to the center line of the point (Fig. 220).
- TRUE-RAKE ANGLE** -The true-rake angle (or "top-rake"), under actual cutting conditions, is the actual slope of the tool face toward the base from the active cutting edge in the direction of chip flow. It is a combination of the back-rake and side-rake angles and varies with the setting of the tool and with the feed and depth of cut (Fig. 221).
- RIGHT-CUT TOOL** -A right-cut single-point tool is one which, when viewed from the point end of the tool, with the face up, has the cutting edge on the right side (Fig. 223).
- LEFT-CUT TOOL** -A left-cut tool has the cutting edge on the left when looking at the point end with the face upward (Fig. 222).



BENT TOOL




FIG. 224

-A bent tool has the point bent to the left or right to make its operation more convenient. These tools are called left-bent tools if the point is bent to the left when looking at the tool from the point end with the face upward and the shank pointing away, and vice versa (Fig. 224).

SIDE-CUTTING-EDGE ANGLE




FIG. 225

-The side-cutting edge angle is the angle between the straight side-cutting edge and the side of the tool shank. In the case of a bent tool, this angle is measured from the straight portion of the shank (Fig. 225).

END-CUTTING-EDGE ANGLE

-The end-cutting edge angle is the angle between the cutting edge on the end of the tool and a line at right angles to the side edge of the straight portion of the tool shank (Fig. 225).

THE SHAPE OR FORM OF THE TOOL AS VIEWED FROM THE TOP

The shape of the tool may be curved, flat or its sides may converge to a sharp point. The form of the tool will depend principally upon the surface being machined. For example, a tool with a curved surface could not be used to produce a rectangular slot or to produce a sharp corner. In contrast, a tool with a sharp corner would not be recommended for a curved surface or for roughing a flat surface.

Usually, there is a difference between the roughing and the finishing tool. In addition, a tool may be offset, or bent to the right or to the left and may feed either in a right-hand or left-hand direction.

A tool with a rounded nose may be used to rough out both steel and cast-iron surfaces, and with slight modification may be used to produce a finish cut. Frequently, the shear-cut tool (Fig. 226) is preferred for finishing steel; whereas, a tool with a flat end shaped as in Fig. 227 is extensively used to finish cast iron.

The three tools illustrated in Fig. 228 should give satisfactory results when used in the shaper to produce flat horizontal surfaces.

The tool shown at (A) is recommended for roughing cut.




FIG. 226





FIG. 227






FIG. 229

It has a side-cutting edge angle of 8° , an end-cutting edge angle of 15° , and a $1/16''$ radius on the nose of the tool. The slight variation of the round-nosed tool shown at (B) is preferred by many for roughing cuts. It has a side-cutting edge angle of 20° and a large radius on the nose. The large radius on the nose is often objectionable if this tool is used for fine cuts, roughing out radii, and in other instances where a broad surface on the tool is likely to produce chatter. This may be overcome by using a tool with a small radius as illustrated at (C).




FIG. 230

Similar in shape to the tool for shaping horizontal surfaces is the roughing tool for down or vertical cutting (Fig. 229). The tool is ground to an angle of about 85° with a small radius on the nose. The side-cutting edge should be parallel with the side of the tool (A) or may be offset slightly (B) to give clearance for the tool holder.




FIG. 231

For finishing cast iron, the tool (A) (Fig. 227) is extensively used and will give excellent results. The corners of the tool may be sharp or they may be rounded slightly as in (B).

Whenever it is desired to finish the surfaces of steel, the shear-cut tool (Fig. 226), when used with a little coolant, will produce a smooth, bright finish.




FIG. 232

In addition to being used to finish cast iron, the square-nosed tool (Fig. 230) can be used to cut slots and to cut-off material. The tool is ground considerably narrower when used to cut-off material, and made to the desired width for cutting slots.

A tool that is used to finish square or acute angular corners is ground as in Fig. 231. This tool is ground at an angle from 5° to 10° less than the angle of the corner which it is intended to cut. As the extreme point of this tool will break down easily, it is not suitable for roughing cuts. For roughing, the nose of the tool should be rounded (Fig. 232).




FIG. 233

Convenient tools for rounding the edge or for cutting the radius of a corner are called radius tools (Fig. 233). These tools are made in two styles to suit either an inside or an outside radius. The inside radius tool (A),




FIG. 234

FIG. 235




FIG. 236

should be ground at an angle of about 85° to give enough clearance for the sides when the inside radius is being cut. Frequently this radius can be cut out with the nose of the round-nosed roughing tool. The corners of the outside radius tool (B), also should be given a slight relief to prevent it from cutting into the adjoining flat surfaces.

As it is necessary at times to shape both sides of a job without taking the work out of the vise or the machine, tools are made to cut on the right-hand or left-hand side of the work. These tools are referred to as: right-hand, left-hand, right-cut or left-cut tools.

According to the American Standards Association definition, "A right-cut single-point tool is one which, when viewed from the point end of the tool, with the face up, has the cutting edge on the right side" (Fig. 234). "A left-cut tool has the cutting edge on the left when looking at the point end with the face upward" (Fig. 235).

Here again, terminology and use of shaper tools are not entirely consistent with these definitions. Some manufacturers still prefer to designate these in the opposite manner.

The same situation exists with the bent tools. In American Standards terminology, right and left single-point tools are designated as in Fig. 236. At the same time, some users still favor the old method of naming them oppositely. However, the important characteristics such as clearance, rake, cutting angles, and shapes are fairly well established for the shaper operator.

CLEARANCE, RAKE AND LIP ANGLE

The purpose of clearance, both on the side and the end of the shaper tool, is to allow the cutting edge to do the cutting and the back of the cutting edge to clear the work.




FIG. 237




FIG. 238




FIG. 239




FIG. 240

It should be realized that the shaper tool does not feed sideways into the work during the actual cutting. Therefore, a clearance of 2° to 6° with an average of 4° is usually considered adequate clearance for the side and the end of the tool. The effective clearance would, in the case of a round-nosed tool, be a combination of the side and front clearance measured at the nose of the tool (Fig. 237).

The side slope and back slope, or side rake and back rake (Fig. 238) are more subject to variation than the front and side clearances. It is the amount of side and back rake which has the greatest influence upon the true lip angle of the tool (Fig. 239).

Theoretically, the rake should be ground on the tool to reduce the amount of power required for cutting and to reduce the wear resulting from the enormous pressure required to have the metal chip flow off the work. On the other hand, the least possible rake should be given in order to support the cutting edge and prevent it from wearing and crumbling away.

Thus, there are two opposite requirements: one which requires the edge to be as sharp as possible; the other tends to avoid a sharp cutting edge. The amount of rake must be determined then as a compromise between the above two opposite requirements. The tool should be sharp to cut with maximum efficiency, blunt enough to support the cutting edge, and still be able to produce the desired finish on various metals.

With the foregoing principle in mind, no set rake is satisfactory for all metals and under all conditions. Some very satisfactory results have been obtained with the following rake angles: for steel, a side rake of 10° to 20° and a back rake of 2° to 8° ; for cast iron, a side rake of 3° to 10° and a back rake of 0° to 3° .

Occasionally, a side-cutting tool may be given a negative rake (Fig. 240). As the tool moves forward, it first strikes the work above the extreme point, softening the blow slightly and reducing the tendency to break off the tip of the tool.








The lip angle of the tool is influenced by the amount of rake and the clearance of the tool. For instance, if a tool has 3° clearance on the side and a side slope of 15° , the lip angle at that point will be 72° (Fig. 241).

These tools are ground to be used with a tool holder which holds the tool parallel with the shank (Fig. 245).

Often the only type of tool holder available is one which will hold the tool at a 15° angle of inclination. This angle must be taken into consideration when the tool is ground. If the tool is inclined 15° in the tool holder and a 3° relief angle (front clearance) is required, 15° plus 3° , or an 18° relief angle must be ground on the end of the tool in order to compensate for the 15° slope and to give 3° clearance (Fig. 242).

The same procedure must be followed in regard to the back rake of the tool. Since the tool is set at 15° , the back slope will also be 15° . With a 3° relief, a lip angle of 72° must be ground (Fig. 243). If for cutting cast iron a back relief of 2° were required, then the cutter would be ground on the tip to a lip angle of 85° (Fig. 244).


The side relief and the side rake are also affected by the 15° inclination, but not in the same proportion as are the end relief and the back relief.



The tools as illustrated on this page conform to the terminology of the American Standards Association. The indicated cutting angles and the clearance are to be used when the tool is held parallel with the shank of the holder.

FIG. 248


Left-Cut Roughing Tool For Steel




Left-Cut Roughing Tool for Cast Iron




Left-Side Cut Tool For Steel




Left-Side Cut Tool for Cast Iron




Finishing Tool For Cast Iron -
Corners May be Round




Side-Cutting Tool for Squaring Corners




Round-Nosed Tool for Light
Finishing Cuts on Steel



Round-Nosed Tool For Bronze or Brass



Shear Tool For Finishing Steel



Cutting-Off and Slot-Cutting Tool

